

Test Report

號碼(No.): ETR23A05514 日期(Date): 07-Nov-2023 頁數(Page): 1 of 4

明輝化工實業有限公司 (MIN HUEY CHEMICALS INDUSTRIES CO., LTD.) 新北市土城區大安路138巷32號 (NO. 32, LN 138, DA'AN RD., TUCHENG DIST., NEW TAIPEI CITY 23673, TAIWAN)

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by the applicant as):

送樣廠商(Sample Submitted By) : 明輝化工實業有限公司 (MIN HUEY CHEMICALS INDUSTRIES CO., LTD.)

樣品名稱(Sample Name) : MIN HUEY SCREEN INK (明輝油墨) 樣品型號(Style/Item No.) : 橘色 (無鹵) (ORANGE (NON-HALOGEN))

收件日(Sample Receiving Date) : 31-Oct-2023

測試期間(Testing Period) : 31-Oct-2023 to 07-Nov-2023

測試需求(Test Requested) : 依據客戶指定,測試鹵素-氟、氯、溴、碘。 (As specified by client, to test

Halogen-Fluorine, Chlorine, Bromine, Iodine in the submitted sample.)

測試結果(Test Results) : 請參閱下一頁 (Please refer to following pages).

Troy Chang / Department Malager Signed for and on behalf of Alwah SGS TAIWAN LTD. Chemical Laboratory - Taipei



PIN CODF: 3A04778



Test Report

號碼(No.): ETR23A05514 日期(Date): 07-Nov-2023 頁數(Page): 2 of 4

明輝化工實業有限公司 (MIN HUEY CHEMICALS INDUSTRIES CO., LTD.) 新北市土城區大安路138巷32號 (NO. 32, LN 138, DA'AN RD., TUCHENG DIST., NEW TAIPEI CITY 23673, TAIWAN)

測試部位敘述 (Test Part Description)

No.1 : 橘色油墨 (ORANGE INK)

測試結果 (Test Results)

測試項目	測試方法	單位	MDL	結果
(Test Items)	(Method)	(Unit)		(Result)
				No.1
氟 (F) (Fluorine (F)) (CAS No.: 14762-	參考BS EN 14582: 2016,以離子層析儀分析。	mg/kg	50	n.d.
94-8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
氯 (Cl) (Chlorine (Cl)) (CAS No.:	參考BS EN 14582: 2016 · 以離子層析儀分析。	mg/kg	50	68.2
22537-15-1)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
溴 (Br) (Bromine (Br)) (CAS No.:	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
10097-32-2)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
碘 (I) (Iodine (I)) (CAS No.: 14362-44-	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			

備註(Note):

- 1. mg/kg = ppm; 0.1wt% = 0.1% = 1000ppm
- 2. MDL = Method Detection Limit (方法偵測極限值)
- 3. n.d. = Not Detected (未檢出); 小於MDL / Less than MDL




Test Report

號碼(No.): ETR23A05514 日期(Date): 07-Nov-2023 頁數(Page): 3 of 4

明輝化工實業有限公司 (MIN HUEY CHEMICALS INDUSTRIES CO., LTD.) 新北市土城區大安路138巷32號 (NO. 32, LN 138, DA'AN RD., TUCHENG DIST., NEW TAIPEI CITY 23673, TAIWAN)

鹵素分析流程圖 / Analytical flow chart - Halogen





Test Report

號碼(No.): ETR23A05514 日期(Date): 07-Nov-2023 頁數(Page): 4 of 4

明輝化工實業有限公司 (MIN HUEY CHEMICALS INDUSTRIES CO., LTD.) 新北市土城區大安路138巷32號 (NO. 32, LN 138, DA'AN RD., TUCHENG DIST., NEW TAIPEI CITY 23673, TAIWAN)

* 照片中如有箭頭標示·則表示為實際檢測之樣品/部位. * (The tested sample / part is marked by an arrow if it's shown on the photo.)

ETR23A05514



** 報告結尾 (End of Report) **